

Recalls Results by VIN - Vehicle Identification Number

[Print](#) **VIN:** 1G1ZF57599F255608**Year:** 2009 **Make:** Chevrolet **Model:** Malibu**Number of Open Recalls:** 1**NHTSA Recall Number:** [14V252](#)**Recall Date:** May 14, 2014**Manufacturer Recall Number:** N130036**SUMMARY:**

General Motors has decided that a defect which relates to motor vehicle safety exists in 2004-2012 Malibu, 2004-2007 Malibu Maxx, 2005-2010 Pontiac G6, 2007-2010 Saturn Aura vehicles. On these vehicles, over time an increased resistance can develop in the Body Control Module (BCM) connection system and result in voltage fluctuations or intermittency in the Brake Apply Sensor (BAS) circuit that can cause service brake lamp malfunction. As a result, the service brake lamps may illuminate when the service brakes are not being applied, or may not illuminate when the service brakes are being applied. Additionally, cruise control may not engage. If cruise control is engaged, additional service brake pedal travel may be required to disengage it. Service brake pedal application may not be required to move the shift lever out of PARK, or additional service brake pedal travel may be required to move the shift lever out of PARK. Traction control, electronic stability control, and panic braking assist features, if equipped, may be disabled. Service ESC and/or Traction Control tell-tales may illuminate with this condition.

SAFETY RISK:

These conditions may increase the risk of a crash.

REMEDY:

Dealers are to attach the wiring harness to the BCM with a spacer, apply dielectric lubricant to both the BCM and harness connector and on the BAS and harness connector, and relearn the brake pedal home position free of charge.

RECALL STATUS: Recall **INCOMPLETE****MANUFACTURER NOTES:**

Visit manufacturer website at <https://my.gm.com/recalls> for more information.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Feb 2, 2023

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues & Recalls](#) section and follow the instructions there.

Recall information for this manufacturer is only available going back to August 20, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

 Enter another VIN here:

☐ I'm not a robot

reCAPTCHA
[Privacy](#) - [Terms](#)

Submit